

Can-America PHMGH Inc. 2021 Environmentally Responsible Manufacturer 204-1345 Pembina Highway, Winnipeg, MB R3T 2B6

One Company – One Team <u>www.canerica.net</u>

e-mail: info@canerica.net

Tel 204-771-6711

May 27, 2024

We, Grand Chief Glenn Hudson, and I met at around 11:00 AM at the first white house at the entrance of the Peguis Community.

We inspected the house. A mold smell was appreciated. A visual inspection detected some black mold spots on the first floor and a lot in the basement. The mold smell was stronger (5 on a scale of 1 to 10) in the basement. We believe our product does the job, judging by smell appreciation.

Work performed:

11:10 – 12:15 Sweep the floor of the first floor.

12:15 - 14:24 Sweep the basement and collect 2 pails of water from seepage on the west wall. A bottle with a water sample was taken.

This was in preparation for spraying Stamp Out.

14:30 Mold samples taken with masking tape. B1, B2, B, B4.

15:12 – 15:57 Spraying started in the basement. 24 liters. There was a very strong mold smell after the application in the west wall. 10 on a scale of 1 to 10.

16:10 – 15:38 Spraying on the first floor, 20 liters. Sweeping the floor, 4 liters.

Pictures:

Moisture measurement at the basement.(>40%)

2 pails of water were collected.





1 | Page Feb 02,2023



Can-America PHMGH Inc. 2021 Environmentally Responsible Manufacturer 204-1345 Pembina Highway, Winnipeg, MB R3T 2B6

One Company – One Team

www.canerica.net

e-mail: info@canerica.net

Tel 204-771-6711

Mold samples were taken with masking tape.





6 bottles (24 liters) were sprayed in the full basement.





2 | P a g e Feb 02,2023



Can-America PHMGH Inc. 2021 Environmentally Responsible Manufacturer 204-1345 Pembina Highway, Winnipeg, MB R3T 2B6

One Company – One Team <u>www.canerica.net</u>

e-mail: info@canerica.net

Tel 204-771-6711

The floor was swept. Left 2 boxes (8 bottles) to be used on the next application (Saturday June 1st).

4 liters to seep the floor.





CONCLUSIONS & RECOMMENDATIONS:

- 1. To fix seepage from outside the west wall. Seal or French drainage is suggested.
- 2. There is a leakage from the pipe going out in the west wall that needs to be fixed.
- 3. Must be kept dry the floor on the west wall, all the time.
- 4. Replace the damaged insulation on the east wall, damaged by mice.
- 5. The HVAC is in excellent new condition.
- 6. The supporting west pole is rusted. To be aware of.
- 7. Some woods show mold infection.
- 8. I will ask Dr, Oule to analyze the samples taken.
- 9. Survey mold smell by Thursday, May 30^{th,} and record smell appreciation (1 to 10).
- 10. Next full application by Saturday, June 1st.
- 11. Survey and record smell appreciation by June 8th (scale 1 to 10).
- 12.3rd application by Saturday, June 8th.







Rolando Jeria, <u>P.Eng</u> President & CEO (204) 612 1924 rolando@canerica.net

3 | Page Feb 02,2023