



Can-America PHMGH Inc. 2021  
Environmentally Responsible Manufacturer  
204-1345 Pembina Highway, Winnipeg, MB R3T 2B6

One Company – One Team

[www.canerica.net](http://www.canerica.net)

e-mail: [info@canerica.net](mailto:info@canerica.net)


Tel 204-771- 6711

Jul 07, 2024

### **Summary Report on Stamp Out treatment Peguis Home.**

On May 27, 2024, we met Glenn Hudson at the first white house at the entrance of the Peguis Community to undertake a mold remediation with our product, Stamp Out.

Peguis House location (UTM Google coordinates: 602425.00 m E; 5674885.00 m N)



We inspected the house. A mold smell was appreciated. A visual inspection detected some black mold spots on the first floor and a lot of spots in the basement. The mold smell was stronger in the basement.

We performed 3 applications in the whole house, the first floor and the basement. First one on May 27<sup>th</sup>, the second on Jun 1<sup>st</sup>, and the third on Jun 11<sup>th</sup>.

Each application took about 2 hours. The applications were done with a 12 liters sprayer. 6 bottles (4 liters each) in the first floor and 6 bottles in the basement.



**Can-America PHMGH Inc. 2021**  
**Environmentally Responsible Manufacturer**  
**204-1345 Pembina Highway, Winnipeg, MB R3T 2B6**

One Company – One Team

[www.canerica.net](http://www.canerica.net)

e-mail: [info@canerica.net](mailto:info@canerica.net)

Tel 204-771- 6711



In the first visit, at the West wall of the basement, was flooded. It was collected 2 pails.

Samples of the mold and water were taken for testing at USB lab by our Dr. Mathias Oule.

We noticed that no stain on walls, ceiling, floor was detected.



The smell decreased considerably with the 2<sup>nd</sup> application. This is the good indicator that the mold starts to disappear.



On the third visit we met Rob Forbister, P.Eng Peguis Community, and 3 staff, 2 ladies and 1 gentleman, to get a live demo of the application.

Questions about the price had arisen.

We are not a contractor, but a supplier. I said the retailer product cost is 40 CAD/bottle, 10 CAD/liter. This house completed today 3 applications with 6 bottles per floor, each application. Total 18 bottles per floor, 36 bottles per house, or 9 boxes. Total 1,440 CAD. If local Community people perform at 4 hours per application at 30 CAD/h = 360 CAD. Grand Total = 1,800 CAD per house

We expect the most probable with 2 applications will be sufficient. So,  $12 \times 2 = 24$  bottles,  $4 \times 2 = 8$ h. Total cost should be  $960 + 240 = 1,200$  CAD per house.

The sprayer can be bought for 115 CAD

[https://www.vevor.ca/stainless-steel-sprayer-c\\_10177/1-5gal-6l-stainless-steel-sprayer-curved-lance-3-3-inch-reinforced-hose-fan-tip-p\\_010699118223](https://www.vevor.ca/stainless-steel-sprayer-c_10177/1-5gal-6l-stainless-steel-sprayer-curved-lance-3-3-inch-reinforced-hose-fan-tip-p_010699118223)

### CONCLUSIONS & RECOMMENDATIONS:

1. The seepage on the west wall is still on at the 3<sup>rd</sup> visit.
2. The floor must be kept dry on the west wall, all the time.
3. The smell has decreased considerably. In scale 1 to 10, Basement 3, First floor 1.
4. It is suggested 2 applications/house, in 2 weeks' time frame, summer preferably.



Rolando Jeria, P.Eng  
Chairman of Board  
(204) 612 1924  
[rolando@canerica.net](mailto:rolando@canerica.net)



### Annexes:

1. USB Lab report by Dr. Mathias Oule regarding mold detected.
2. MSDS of Stamp Out.