www.canerica.net

e-mail: info@canerica.net

Tel 204-771-6711

Jun 11, 2024

Report on Second Stamp Out treatment on Jun 11, 2024.

Work performed:

10:30 – 10:45 Meet Rob Forbister, P.Eng Peguis.

10:45 - 12:55 Preparation to spray in basement, 6 bottles. Samples taken. Demo to 3 members of Peguis Community, 2 ladies, 1 gentleman.

12:55 – 14:05 Finished first floor, 6 bottles.

Pictures:

No stain detected. One of the characteristics of the product.



1 | Page Jun 11,2024



One Company – One Team

www.canerica.net

e-mail: info@canerica.net

Tel 204-771-6711

West Wall, corner where leakage is coming, piping going out.







2 | Page Jun 11,2024




One Company – One Team

www.canerica.net


e-mail: info@canerica.net

Tel 204-771-6711





East Wall, cleaned up with a broom (one of the ladies), black spot disappear.





3 | Page Jun 11,2024



One Company – One Team

www.canerica.net

e-mail: info@canerica.net

Tel 204-771-6711


CONCLUSIONS & RECOMMENDATIONS:

- 1. The seepage on the west wall is still on. Rob agreed with this action.
- 2. The floor must be kept dry on the west wall, all the time.
- 3. Rob asked for the cost of remediation.

We are not a contractor, but a supplier. I said the retailer product cost is 40 CAD/bottle, 10 CAD/liter. This house completed today 3 applications with 6 bottles per floor, each application. Total 18 bottles per floor, 36 bottles per house, or 9 boxes. Total 1,440 CAD. Assuming 4 hours per application at 30 CAD/h = 360 CAD. Grand Total = 1,800 CAD. This house was in bad shape. I expect the most probable with 2 applications will be sufficient. So, 12X2 = 24 bottles, 4x2 = 8h. Total cost should be 960 + 240 = 1,200 CAD.

The sprayer can be bought for 115 CAD

https://www.vevor.ca/stainless-steel-sprayer-c_10177/1-5gal-6l-stainless-steel-sprayer-curved-lance-3-3-inch-reinforced-hose-fan-tip-p_010699118223



4. The smell has decreased considerably. Basement 3, First floor 1, scale 1 to 10.



Rolando Jeria, <u>P.Eng</u> President & CEO (204) 612 1924 <u>rolando@canerica.net</u>



